Technical Bulletin Model 911 Turbo 8 Subject: Alternator - A/C Compressor Belt Squeal on Cold Start Model 911 Turbo 8 Part Identifier 8725 Number 9203

ATTENTION: Service Manager/Service Technician

This bulletin replaces Technical Bulletin, Group 8, Number 9203, dated 6-30-92.

Models Affected:

911 Turbo 1991 (M) and 1992 (N) models

Concern:

Squeal from alternator - A /C compressor belt after cold start of the

engine.

General Information:

To eliminate belt squeal during cold start, the alternator – A/C compressor belt is now longer and routed differently over the drive pulleys. The new belt is identified by the marking "6k 1554" printed on the belt (See Figure 1).



Figure 1

Parts Information:

New version belt Part Number 999 192 365 50

Former version belt Part Number 999 192 356 50 (no longer

available)

New alternator - A/C compressor belts were introduced into vehicle production as of April 29, 1992, beginning with engine

number 61 N 01442 M30.69.

Repair Information:

When complaints of squeal from the alternator drive belt are made, or when replacing the former version belt, the new version belt must

be installed and the tension set with special tool 9201.

- 1. The engine must be cold.
- 2. Install new version belt following the routing shown in Figure 2.




Figure 2



Technical Bulletin		Model 911 Turbo	Group 8	
Subject:	Alternator – A/C Compressor Belt Squeal on Cold Start	Part Identifier 8725	Number 9203	

Repair Information (cont.):

3. Remove the circlip retaining the rollers to the measuring pin of special tool 9201 (Figure 3) and remove rollers.




Figure 3

4. Measure the belt tension at the arrow location shown in Figure 2 and set the tension according to the belt thickness using the values below:

Belt thickness Tool 9201 scale units
5.0 - 5.3mm 3.0 scale units
5.4 - 5.5mm 4.0 scale units
5.6 - 5.8mm 4.5 scale units

If the minimum value belt thickness of 5.0mm cannot be obtained, a thickness (feeler) gauge may be inserted between the belt and special tool 9201 measuring pin. Do not exceed a total belt thickness of 5.8mm.

*Note: Belt thickness can be measured using a vernier caliper.

Measurement should be taken at the arrow location in

Figure 2.

Start the engine and accelerate lightly two-to-three times. Turn off the engine and recheck the belt tension. Readjust if necessary.

