Technical Bulletin Model All 6 Subject: Air Bag Faults Model All 6 Part Identifier Number 6863 9305

ATTENTION: Service Manager/Service Technician

Models Affected:

All Porsche Models 1992-on

Concern:

Fault diagnosis of air bag system.

General Information:

There has been some confusion in diagnosis of air bag faults on 1992 and later vehicles. When using Porsche special tool 9288 for air bag diagnosis, **ALL** of the information for a particular fault must be obtained and noted before diagnosis of the fault begins. This means the DTC (Diagnostic Trouble Code) number and the description of the fault as the 9288 reads it should be noted.

On models 928 and 911 from model year 1992, the DTC does not match the fault codes listed with the **test points** in the Workshop Manual. However, the description of the fault is accurate. On all 1992 and later vehicles, the DTC description of the fault and test points may be found in the 968 Workshop Manual, Volume III, pages D68-7 to D68-13.

Fault description, DTC and test points for 1990 to 1991 vehicles are found in the appropriate Workshop Manual for that particular model.

The following fault codes and descriptions apply to all Porsche models 1992 and later.

Fault Code Fault Description



10	Ignition circuits	 closed once closed several times permanently closed contact resistance to U_B contact resistance to ground couplesd 1/3 or 2/3
11	Left front sensor	 resistance too high
12	Right front sensor	- resistance too high
21	Ignition pill circuit 1	- resistance too high /too low
22	Ignition pill circuit 2	- resistance too high /too low
23	Ignition pill circuit 3	- resistance too high /too low
30	Warning light air bag	- signal implausible
31	Warning light air bag	- control unit defective
40 to 47	Warning light air bag	- control unit defective
50 to 54	Warning light air bag	- control unit defective
60 to 62	Warning light air bag	- control unit defective
70	Crash entry	- only if air bag has been triggered
	Side i Sili y	orny in an bag has been anggered