Technical Bulletin | Model | Group | 911 turbo | 1991-92 | | | Subject: | Spark Plug Usage | 2870 | 9103 | |

ATTENTION: Service Manager/Service Technician

Models Affected:

911 turbo 1991-92

Concern:

1991-92 911 turbo engines can be equipped with either WR 4 DPO or WR 6 DPO spark plugs. The WR 6 DPO spark plugs started in production July 1991. The WR 6 DPO spark plug is preferred for cars used on frequent short trips or cars that are infrequently run since this plug reaches a self-cleaning temperature more quickly than the WR 4

DPO.

The WR 4 DPO and the WR 6 DPO can be used interchangeably, but

they must not be mixed on an engine.

Parts Information:

WR 4 DPO - Part Number 999 170 186 90 WR 6 DPO - Part Number 999 170 190 90

